

6. RECOMMENDATIONS

The following provisional recommendations are made with a view to identifying improvements to target the root causes and contributory factors which resulted in the G4 incident:

1. The Safety Case should be reviewed and revised as required.
2. Emergency response processes in relation to well incidents should be reviewed, and the feasibility of additional mitigation measures should be considered and implemented if appropriate.
3. The process for well operations risk assessment should be reviewed and revised if required.
4. The process for well operations MOC should be reviewed and revised if required.
5. Ongoing geo-mechanical and geo-science studies should be continued in relation to gas migration from and within the Chalk formation.
6. The AMS design, operating philosophy and procedure should be reviewed and revised if required.
7. Annulus intervention processes for Elgin Franklin wells should be reviewed and revised if required.
8. Ongoing investigations into the causes of the casings failures should be continued.
9. The Well Examination Scheme (L2-MTH-00-012) should be reviewed and revised if required.

This page is intentionally blank